
## XPAND REACH



## 120° Station – Assembly Instructions




For additional assembly support, refer to www.openplan.com or contact 844.OPS.OPS1

## XPand Parts Used for Assembly

Item	Part name	Part Description	Image
1	XP-LA	Leg Assembly	
2	XP-SB-Bracket	Stretcher Bar Bracket	
3	XP-LR-XX	Leg Rail, XX"	
4	XP-WSSA-XX	Work Surface Support Arm, Double	
5	XP-LRC-XX"	Leg Rail Cover XX"	
6	XP-SB-XX	Stretcher Bar, XX"	
7	XP-CTA-XX	Cable Tray	

Item	Part name	Part Description	Image
8	XP-120-Inside	120 Inside Bracket	
9	XP-CTC	Cable Tray Clip	
10	XP-WSSB	Work Surface Support Bracket	
11	XP-WS-Glide	Glide for Work Surface	
12	XP-CWSXXXX	120 Degree Work Surface	
13	XP-SCREWS	5/16-18 x .5" Hex Socket Cap Screw	
14	XP-SCREWS- WS	10-9X1 PH Pan Head, ST P'bd Screw, ZP	

XPand offers two types of end legs, Tapered legs and Rectangular legs. Though the legs look different, the assembly process is same.




<u>Step 1</u>: Prepare a large floor space to put the XPand order together. Unpack the parts and check to see if all the XPand parts are present as per the sales order pick list.

<u>Step 2</u>: Assemble the Leg Assembly (XP-LA) to the Leg Rail (XP-LR-XX) using (2) XP-Screws.




<u>Step 3</u>: Assemble another XP-LA to the other end of the Leg Rail using (2) XP-Screws.




<u>Step 4</u>: Assemble the XP-SB-Brackets to the Leg Rail using (3) XP-Screws per Bracket. Make sure the Top Surface of the Bracket faces upwards. Figure A shows the Top surface of the Bracket.


<u>Step 5</u>: Assemble the XP-SB-XX (Stretcher Bars) to the XP-SB-Brackets using (2) XP-Screws per Bracket.


Note: The Stretcher bar is 5" shorter than the specified size. For example, XP-SB-60 is actually 55" long.







 $\underline{\text{Step 6}}\text{:}$  Assemble (3) XP-120-Inside Bracket to (3) XP-LA using (2) XP-Screws per Leg.









<u>Step 7</u>: Assemble (2) XP-120-Inside Bracket Assembly to Stretcher bar using (2) XP-Screw per Bracket.





<u>Step 8</u>: Place Work Surface Support Arms (XP-WSSA-XX) on either side of the Stretcher bar and assemble it with the (2) XP-Screws per arm.




Note: If the Stretcher bars are longer than 48" long, assemble (1) XP-WSSB to the center of the Stretcher bar using (1) XP-Screw as a Set Screw. No XP-WSSB is used for Stretcher bars less than 48".





<u>Step 9</u>: Repeat Step 2 to Step 5 to build (2) more End Leg Assembles with Stretcher bars. Repeat Step 7 and Step 8 to assemble the Stretcher bars to XP-120-Inside Bracket to get a 120 degree (3) pod.

Note: To build a 120 degree (6) Pod, repeat Step (2) to Step (9) and don't assemble one of the End Leg Assembly yet. Connect (2) 120 degree (3) pods with a XP-MLC using (2) XP-Screws per connector.




Step 10: Slide Cable Tray Clips onto the Cable Trays.





Step 11: Secure the assembled Cable Tray Clips to the Stretcher Bar



Note: If you want the Work Surface to slide using the glides, don't screw the Work Surface to the XP-WSSB.

Step 12: Place the Work Surface on XP-WSSA-XX and center it over the large hole in the XP-WSSA-XX. Leave ½" overhang on each side edge. Using XP-Glides and the Work Surface screws (Shown in Figure E), secure the Work Surface to the XP-WSSA-XX using (4) Work Surface Screws (XP-SCREWS-WS) per arm.

