

XPAND REACH



Double Bench: Multiple Station-Return Glass-Assembly Instructions







For additional assembly support, refer to www.openplan.com or contact 844.OPS.OPS1

XPand Parts Used for Assembly

Item	Part name	Part Description	Image
1	XP-LA	Leg Assembly	No. of the last of
2	XP-SB-Bracket	Stretcher Bar Bracket	
3	XP-LR-XX	Leg Rail, XX"	
4	XP-WSSA-XX	Work Surface Support Arm, Double	
5	XP-LRC-XX"	Leg Rail Cover XX"	
6	XP-SB-XX	Stretcher Bar, XX"	
7	XP-MLC	Mid Leg Connector	
8	XP-G-RSB-EC	Glass Channel End Bracket for Return Screen	

Item	Part name	Part Description	Image
9	XP-G-XX	Glass, XX"	
10	XP-CTA-XX	Cable Tray	
11	XP-CTC	Cable Tray Clip	
12	XP-WSSB	Work Surface Support Bracket	
13	XP-WS-Glide	Glide for Work Surface	
14	XP-TXXXX	Work Surface	
15	XP-SCREWS	5/16-18 x .5" Hex Socket Cap Screw, FT, SS	
16	XP-SCREWS- WS	10-9X1 PH Pan Head, ST P'bd Screw, ZP	






<u>Step 1</u>: Prepare a large floor space to put the XPand order together. Unpack the parts and check to see if all the XPand parts are present as per the sales order pick list.


<u>Step 2</u>: Attach the Leg Assembly (XP-LA) to the Leg Rail (XP-LR-XX) using (2) XP-Screws.




<u>Step 3</u>: Attach another Leg Assembly to the other end of the Leg Rail using (2) XP-Screws.




<u>Step 4</u>: Assemble (2) XP-SB-Brackets to the Leg Rail using (2) XP-Screws per Bracket. Make sure the Top Face of the Bracket faces upwards. See Figure A.






<u>Step 5</u>: Assemble the Stretcher Bars (XP-SB-XX) to the XP-SB-Brackets using (2) XP-Screws per Bracket.



<u>Note</u>: The Stretcher bar is 5" shorter than the specified size. For example, XP-SB-60 is actually 55" long.


<u>Step 6</u>: Assemble (2) XP-MLC-S (Mid Leg Connector with Spacer) to the XP-LA legs using (2) XP-Screws per Leg.






<u>Step 9</u>: Place Work Surface Support Arms (XP-WSSA-XX) on either side of the Stretcher bar and assemble it with the (2) XP-Screws per arm.


 $\underline{\text{Step 10}}\text{:}$ Slide in the Cable Tray Clips onto the Cable Trays.



<u>Step 11</u>: Secure the assembled Cable Tray Clips to the Stretcher Bar.

<u>Step 12</u>: Assemble XP-G-RSB to XP-MLC-S using (2) XP-Screws (shown in Figure B)







<u>Step 13</u>: If the Stretcher bars are longer than 48", assemble (1) XP-WSSB to the center of the Stretcher bar using (1) XP-Screw as a Set Screw.

Note: No XP-WSSB is used for Stretcher bars less than 48".

 $\underline{\text{Step 14}}:$ Assemble the Metal End Caps (XP-G-RSB-EC) on either ends of the Extrusion (XP-G-EXX) using (1) XP-Screw per End Cap.



<u>Step 15</u>: Place the Extrusion in flush with the width of the Work surface and assemble the Extrusion to the Work Surface using (1) XP-Screw-WS per end cap



Step 16: Place the Work Surfaces on the support brackets and position them 1.5" apart, centered over the large hole in the XP-WSSA-XX. Leave ½" overhang on each side edge (as shown in Figure B). Secure the Work Surface to the XP-WSSA-XX using (4) glides & (8) Work Surface Screws (XP-SCREWS-WS) per arm (Shown in Figure C & D). Make sure the bottom of the extrusion is placed on the XP-G-RSB (Shown in Figure E).

Note: If you want the Work Surface to slide using the glides, don't screw the Work Surface to the XP-WSSB.

