Power Entry Kits (PEK) available from HMU can be either left or right handed with a 6' flexible covered wiring (whip). The PEK will attach onto the power harness at either receptacle locations (left or right) by snapping into the receptacle housing. This allow maximum use of the whip length. The arrow on the right side of the PEK must be pointing up to connect it into the receptacle housing





Left going left



Right going left




Right going right



Left





Right



